

# BGO INDUSTRIES LTD.

## Inspection Report

Product: PVC TARPALIN OF WATER TANK

THICKNESS: 1.0MM

SIZE: 60CMX60CM

Report No. (WJB-2119)

Date: 2017-11-15

NO.	ITEM NAME	STANDARD REQUEST	TEST RESULT	SIGNAL JUDGE
1	SURFACE	Basic fabric cutting yarn should not be scattered	Fit for request	Qualified
2	PHYSICAL PROPERTY			
2.1	Longitudinal tensile strength N/50MM	$\geq 1470$	1628	Qualified
2.2	Transverse tensile strength N/50MM	$\geq 1470$	1612	Qualified
2.3	Longitudinal elongation %	$\geq 40$	17	Qualified
2.4	Transverse elongation %	$\geq 40$	17	Qualified
3	Heat resistance	< +60C No Abnormal	No adhesion, cracks, etc.	Qualified
4	Cold resistance	< -20 C No Abnormal	No Cracks.	Qualified

Pictures: 500 ML Water Tank



Contact Name: Virginia

BGO INDUSTRIES LTD.

E-mail: [export@bgo-industries.com](mailto:export@bgo-industries.com)

Whatsapp: +86 18012683155

Skype: virginiale881